

Apex Rack without Stack Weight




| | Parts list 1 | | | | | | | |
|-------|----------------------------|-------|-------------------------|-------|-------------------------|--|--|--|
| | | | | | | | | |
| NO.1 | Column *4pcs | NO.2 | Front crossbeam *1pc | NO.3 | Rear crossbeam *1pc | | | |
| | | | | 0 | 99999999 | | | |
| NO.4 | Hanging plate rod *6pcs | NO.5 | Safety pole *A pair | NO.6 | Side crossbeam *4pcs | | | |
| | | | | | | | | |
| NO.7 | Handle group *A pair | NO.8 | | NO.9 | | | | |
| | | | | | | | | |
| NO.10 | | NO.11 | | NO.12 | Marigan 100 Salah Maja | | | |
| NO.13 | | NO.14 | | NO.15 | | | | |
| | | | | | | | | |
| NO.16 | | NO.17 | | NO.18 | Tu- | | | |

| | Parts list 2 | | | | | | | |
|-------------------|----------------------|---|-------------------|----|---|--|--|--|
| | | | | | | | | |
| А | M16 washer *76pcs | В | M16 nut *38pcs | С | External hexagonal screw M16X110*38pcs | | | |
| | | | | | | | | |
| | | į. | | | | | | |
| | | | | | | | | |
| | 1 | -0.00 | | | | | | |
| | | | | | | | | |
| \$4.000 mg 400,00 | | p 100 100 100 100 100 100 100 100 100 100 100 100 100 | | į. | Martini ng 1 san sy 1 syr-Auri | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| Assembly steps | | | | | | | |
|----------------|---------|-------------------------------------|-----|---------|----------------|-----|--|
| Step NO | Item NO | Name | Qty | Item NO | Name | Qty | |
| | Α | M16 washer | 40 | 1 | Column | 4 | |
| | В | M16 nut | 20 | 3 | Rear crossbeam | 1 | |
| 1 | С | External hexagonal screw M16X110 | 20 | 6 | Side crossbeam | 4 | |
| 1 | | | | | | | |
| | | | | | | | |
| | | | | | | | |



| Assembly steps | | | | | | | |
|----------------|---------|----------------------------------|-----|---------|-----------------|-----|--|
| Step NO | Item NO | Name | Qty | Item NO | Name | Qty | |
| А | Α | M16 washer | 20 | 2 | Front crossbeam | 1 | |
| | В | M16 nut | 10 | 7 | Handle group | 2 | |
| 2 | С | External hexagonal screw M16X110 | 10 | | | | |
| | | | | | | | |
| | | | | | | | |



| Assembly steps | | | | | | | |
|----------------|---------|-------------------------------------|-----|---------|-------------------|-----|--|
| Step NO | Item NO | Name | Qty | Item NO | Name | Qty | |
| 3 | А | M16 washer | 16 | 4 | Hanging plate rod | 4 | |
| | В | M16 nut | 8 | 5 | Safety pole | 2 | |
| | С | External hexagonal screw M16X110 | 8 | | | | |
| | | | | | | | |
| | | | | | | | |

